

Heritage Review – 2016 to 2017 Inventory Changes Tracked

Drummond, Queensberry, Lygon & Victoria St Block



Drummond St	HO No	2016	2017
1	HO1	A1	Significant/Significant
3	HO1	A1	Significant/Significant
5	HO1	A1	Significant/Significant
7	HO1	A1	Significant/Significant
9	HO1	A1	Significant/Significant
11	HO1	A1	Significant/Significant
13	HO1	A1	Significant/Significant
15	HO1	C1	Significant/Significant
17	HO1	C1	Significant/Significant
19	HO1	C1	Significant/Significant
21-23	HO1	A1	Significant/Significant
25	HO1	A1	Significant/Significant
27	HO1	A1	Significant/Significant
29	HO1	C1	Significant/Significant
31	HO1	C1	Significant/Significant
33	HO1	C1	Significant/Significant
35	HO1	C1	Significant/Significant
37-39	HO1	A1	Significant/Significant
41-43	HO1	A1	Significant/Significant
45	HO1	A1	Significant/Significant
47	HO1	A1	Significant/Significant
49	HO1	C1	Contributory/Significant
51	HO1	C1	Contributory/Significant
53	HO1	C1	Contributory/Significant
67	HO1	C1	Contributory/Significant
69	HO1	C1	Contributory/Significant
Victoria St			
50-52	HO1092	-	Significant/-
Lygon St			
2	HO68	A1	Significant/-
42-54	HO1	A2	Significant/-
Queensberry St			
59	HO90	A1	Significant/-



The Trades Hall Building – not a significant streetscape?